



HYGIENETECH

Hygiene Technologies International, Inc.

3625 Del Amo Boulevard, Suite 150
Torrance, California 90503-1543
(310) 370-8370
(310) 370-7026 FAX
www.hygienetech.com

July 1, 2008

State of California Board of Equalization
450 N Street
Sacramento, California 94279

Document No. 20807001.1

Attention: David Gau

Regarding: Review of *Microbial Assessment and Mitigation Procedures for 320 Break Room Area*

Dear Mr. Gau:

On June 29, 2008, Hygiene Technologies International, Inc. (HygieneTech) received a copy of the "Microbial Assessment and Mitigation Procedures for 320 Break Room Area" prepared by BioMax Environmental, LLC dated June 26, 2008. Upon review of said document, HygieneTech concurs with the recommendations presented but has the following question.

- 1) Can BioMax provide an opinion as to whether the "significantly elevated" airborne spore levels detected within Break Room 320 was a persistent condition or rather an anomaly that had occurred due to increased non-routine events that may have taken place some time prior to the samples being collected?

If you have any comments or questions, please feel free to contact our offices directly at (310) 370-8370.

Sincerely,

HYGIENE TECHNOLOGIES INTERNATIONAL, INC.

Kenny K. Hsi, CIH
Technical Director